

Software Update 1.3.1.

A firmware update has been created for the remote control
ACEX9005 - 2030036654.

The revised firmware version is:

- Remote control - Firmware 1.3.1.

The firmware update includes general improvements and optimisations of the following functions.

Fixed an error that occurred when saving the statistical data.

The date of the last hygiene flush and last thermal disinfection was incorrectly calculated and saved in the CSV file.

The calculation of the data is now correct.

In the German and English language files, Franke setting to setting has been changed.

Other languages are not affected.



Performing a firmware update for the remote control:

- Transfer update via USB memory mode (see remote control instructions)
- Firmware Update tapreader-1-3-1.bin Select the remote control and Follow the instructions of the remote control.

- Transfer and replace the language files "language files 1.3.1" in the USB memory mode in the main folder.

Software Update 1.3.0.

A firmware update has been created for the remote control
ACEX9005 - 2030036654.



The revised firmware version is:

- Remote control - Firmware 1.3.0.

The firmware update includes general improvements and optimisations of the following functions.

1. Removal of FRANKE – Logo.
2. The parameter "**Dynamic hygiene purge**" was added.

The parameter can be set in the following sequence programmes:

- 0X Tap Menu
- 1X Shower Menu
- 2X WC Menu
- 3X Urinal Menu
- 8X Hygiene Unit Menu

Description:

If "Dynamic hygiene purge" (**on**) is activated, the hygiene purge is operated after the completion of preset hygiene interval time from the moment of previous tap activation.

If "Dynamic hygiene purge" (**off**) is deactivated, a hygiene purge is operated after the preset hygiene interval time, independent of any previous tap activation.

The start time of the hygiene interval time is determined by the moment the power supply is connected to the tap or by a manually triggered hygiene purge.



3. Infrared communication has been optimised.

Reading out and sending the complete settings is now much faster.
The information content remains identical with the previous firmware version 1.2.0.

The language files have been improved and must be exchanged for the update.

Performing a firmware update for the remote control:

- Transfer update via USB memory mode (see remote control instructions)
- Firmware Update tapreader-1-3-0.bin Select the remote control and Follow the instructions of the remote control.

- Transfer and replace the language files "language files 1.3.0" in the USB memory mode in the main folder.